


## Cantilever BQ Wall Mount Arms

THE FOLLOWING ITEMS WERE PUT INTO THE MISCELLANEOUS PARTS BOX FOR THIS ASSEMBLY:

005096	5X5 ANCHOR PLATE	8 PCS
016513	5/16 HEX NUT, ZINC	8 PCS
016529	5/16 LOCKWASHER	8 PCS
076876	5/16-18 X 5 HHCS	8 PCS

IF POSSIBLE, LOCATE THE HOLES 1" INSIDE BOTH EDGES OF A SINGLE 46" PANEL (THE OUTSIDE HOLES OF THE COND. UNIT ARE 44" WIDE).

BALLY WALL PANELS WILL NOT SUPPORT A TWO FAN CONDENSING UNIT.



FIND THE LOCATIONS OF YOUR PANELS' STRAPS AND POCKETS ON THIS DIAGRAM. DO NOT DRILL CLOSE TO THESE ELEVATIONS.

